

Town of Munjor  
Munjor  
Ellis County  
Kansas

HABS NO. KS-39

HABS  
KANS.  
26-MUNJ,  
1-

PHOTOGRAPHS

HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey  
Heritage Conservation and Recreation Service  
Department of the Interior  
Washington, D.C. 20243



United States Department of the Interior  
Heritage Conservation and Recreation Service  
Washington, DC. 20243

NATIONAL ARCHITECTURAL AND ENGINEERING RECORD  
HISTORIC AMERICAN BUILDINGS SURVEY

ARCHITECTURAL DATA FORM

HABS  
KANS  
26-MU  
1-

STATE KANSAS	COUNTY ELLIS	TOWN OR VICINITY MUNJOR
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) TOWN OF MUNJOR		HABS NO. KS-39
SECONDARY OR COMMON NAMES OF STRUCTURE		
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)		
DATE OF CONSTRUCTION (INCLUDE SOURCE)	ARCHITECT(S) (INCLUDE SOURCE)	
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE)		
STYLE (IF APPROPRIATE)		
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)		
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)		
EXTERIOR FEATURES OF NOTE		
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)		
MAJOR ALTERATIONS AND ADDITIONS WITH DATES		
PRESENT CONDITION AND USE		
OTHER INFORMATION AS APPROPRIATE SEE ATTACHED SHEETS FOR INDIVIDUAL DESCRIPTIONS OF THE STRUCTURES.		
SOURCES OF INFORMATION (INCLUDE LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)		
COMPILER, AFFILIATION SUSAN McCOWN, HISTORIAN, HISTORIC AMERICAN BUILDINGS SURVEY		DATE 5/12/80

#### St. Francis Church:

The Gothic style church, located on Moscow Street, is constructed of rough-textured stone. The front elevation consists of a recessed tower with decorative dentil-like stone work, and a triple pointed arch opening containing a religious sculpture of a man. Above it is a flat steeple with pointed arch louvered openings and battlements. The original pointed steeple was removed at an unknown date. A gable roof covers the church.

#### T-Shaped Frame House:

This one-and-a-half story T-shaped frame house was built circa 1916. The walls are clapboarded. Enclosed porches are supported by narrow columns. Intersecting gable roofs shelter the house. A post-rock fencing is in the yard area of the house (See the photo, HABS No. KS-39-3).

#### Circular Outbuilding:

The clapboard-clad circular outbuilding has a wooden shingled roof and a simple finial.